



Immediate Action Required

Stop Use/Recall

**Products:****Select 3M™ DBI-SALA® ShockWave™2 Arc Flash Shock Absorbing Lanyards****Impacted Dates:**

Prior to June 2022

3M Fall Protection is issuing a “Stop Use / Recall” notice for select 3M™ DBI-SALA® ShockWave™2 Arc Flash Shock Absorbing Lanyards.



As part of 3M Fall Protection's ongoing commitment to delivering high quality safety equipment, we are notifying our customers of the following information related to specific 3M™ DBI-SALA® ShockWave™2 Arc Flash Shock Absorbing Lanyards. During an internal review, 3M Fall Protection has identified a potential manufacturing issue with a limited number of devices. This manufacturing issue could result in the lanyard not performing properly in the event of a fall, which could result in severe injury or death. Please reference Appendix A for products that are impacted by this notice. There have been no reports of injuries, accidents, or complaints associated with this issue.

End Users

Please follow the steps listed below:



Step 1: Locate the label on the device (see images at right) to determine the model number. If the device is an impacted model (reference Appendix A), remove the product from service.

Step 2: Once you have confirmed the part number, go to www.ShockWaveRecall.com and follow the instructions to return your device. As soon as a replacement product solution is available, 3M will replace your device, as per our standard warranty. Additional details can be found at the website listed above.

Distributors

Upon receipt of this Notice, please contact our Customer Service department for a listing of the affected ShockWave™2 Arc Flash Shock Absorbing Lanyards sold to you. If you have any of the affected devices in stock, please return them to 3M Fall Protection for credit at 3M's expense. Please immediately forward this Notice to any of your customers who have purchased affected products from you and provide any assistance requested by your customers to complete the process.

A copy of this Notice can be found: www.ShockWaveRecall.com.



Example labels: Above, CSA; Below, ANSI

After visiting www.ShockWaveRecall.com if you still have any questions please contact our Customer Service Team:

US: Call 1-833-638-2697 or email 3musfbserviceaction@mmm.com

Canada: Call 1-833-998-2243 or email 3mcafperviceaction@mmm.com

3M remains committed to providing quality products and services to our customers. We apologize for any inconvenience that this situation may cause you. We appreciate your continued support of 3M Fall Protection products and services.

Appendix A: Affected 3M™ DBI-SALA® ShockWave™2 Arc Flash Shock Absorbing Lanyards
Date of Manufacture: Prior to June 2022

Part Number		Description: 3M™ DBI-SALA® ShockWave™2 Arc Flash Shock Absorbing...	Leg Style
1224610	1244612	... Lanyard	Single Leg
1224612	1244613		
1224613	1244615		
1244610	1244618		
1244610B			
1244610C	1244637C	... Lanyard, Choker	Single Leg
1224611	1244616		
1244611	1244617		
1244614			
1244611B			
1244611C		... 100% Tie-Off Lanyard	Twin Leg
1224630	1244632		
1224632	1244633		
1224633	1244636		
1244630	1244639		
1244630B	1244632B	... 100% Tie-Off Lanyard, Choker	Twin Leg
1244630C	1244641C		
1224631	1244634		
1224634	1244635		
1244631	1244638		
1244631B	1244634B		
1244631C	1244638C		
1244640C			

3M remains committed to providing quality products and services to our customers. We apologize for any inconvenience that this situation may cause you. We appreciate your continued support of 3M Fall Protection products and services.